ABOUT THE PROJECT

This 16th century tomb of the Kokaltash family is of a unique design and plan inspired by the Iranian garden pavilions and later used for the Diwan-i-Khas and Diwan-i-Am at the Red Fort. The structure is set in its own enclosure and comprises of 25 domed chambers supported on 64 marble columns. Repairs commenced in 2011 and eight domes had been repaired by 2012. Each dome required complete dismantling of the marble blocks followed by repairs to marble and masonry prior to restoring blocks to their original position.







Nizamuddin Urban Renewal Initiative

La People Public - Private Partnership Archaeological Survey Of India - South Delhi Municipal Corporation - Central Public Works Department **Aga Khan Foundation - Aga Khan Trust For Culture** For more information, visit: www.nizamuddinrenewal.org or www.facebook.com/NizamuddinRenewal



HISTORICAL SIGNIFICANCE







A R C H I V A L R E S E A R C H



Studies were carried out to achieve better understanding of the historic fabric of the building and its relation with one of oldest precinct in Delhi. Architectural data was collected from Zafar Hasan's – "Monuments of Delhi (Vol. 2) DELHI ZAIL listing", Carr Stephen's - "The Archaeology and Monumental Remains of Delhi" and Ebba Koch's - " Mughal Architecture" and classified for further referencing timeline of the monument was established and all archival paintings

and images were collected and

compared for evidences.



Material Deterioration due to past repairs in white cement masking the damage but allowing the deterioration to accelerate

Chipping of Marble elements like domes, arches, facade, pendentives, jaalis and column capitals

Rusting of iron dowel due to water seepage led to bursting of the marble

B E F O R E CONSERVATION

The marble blocks of the 25 domes were tied to one-another and embedded in the brick masonry over the domes with iron dowels. The rain water spouts from the inaccessible roof got blocked resulting in large quantities of rain water collecting on roof. This resulted in the rapid deterioration of the roof and large scale water ingress from the roof leading to the corrosion, rusting and expansion of the iron dowels. The significant pressure from the expanding iron dowel led to bursting of the marble blocks in all parts of the mausoleum – domes, arches, facade, pendentives and even the column capitals – threatening structural failure and collapse of the structure.





THE SETTING

The masonry wall built in the 1980's to limit access to Chausath Khamba was dismantled and replaced with a transparent fence using motifs from the decorative lattice screens of the mausoleum.

The forecourt itself was paved with stone in a manner that not only enhanced the historic character but also allowed the creation of a performance space for concerts and cultural festivals. Twice a year the Urs ceremony of Hazrat Nizamuddin Auliya and his favourite disciple, the Sufi poet Amir Khusrau is held at the Urs Mahal built within the enclosure in the mid-20th century. It is proposed to install a permanent exhibit in this space.





	1	5.5	5.8	28	8
and the second second and the second s	2	4.4	2.2	18	2
Stone-by-Stone condition	3	3.2	2.4	4	6
assessment of the domes, exterior	4	2.9	5	9	3
and interior façades of the	5	2.8	5.4	4	-
monument was done manually on	6	4.1	3.1	1	-
the images by visual inspection	7	4.1	2.2	3	1
of each stone its defects and its	8	1.5	1	3	2
causes. Past, yet recent, repairs	9	5.12	2.7	13	3
at Chausath Khamba included	10	2.9	2.8	25	7
filling cavities created by broken	11	3.3	1	23	15
marble edges with white cement.	12	6.4	3.1	4	3
This needed to be carefully	13	2.8	1.6	3	2
removed.	14	2.6	1.3	2	2
	15	4.1	4	4	3
Each stone was closely inspected	16	3.5	1	3	-
to list required repairs by	17	1	1.1	2	-
indenting or to assess if it is not	18	2.8	1.3	7	
possible to repair and requires	19	3.1	1.7	5	6 -
replacement.	20	1.5	2	8	4
	21	2.3	1	9	8
	22	1.1	1	2	5
	23	2.2	2	2	3
	24	2.4	1	3	1
	25	1.1	1	7	1





Plan generated using 3D laser scanning data



DOCUMENTATION

A high definition survey, using 3D laser scanning technology, was carried out on the structure as a precursor to conservation works. This was followed with a stone-by-stone assessment of the entire structure to map the profile and defects on each individual stone coupled with photo and video documentation. To complete a structural analysis pits were dug to study the foundations – which were surprisingly found to reach a depth greater than five metres.



(Above) 3D Laser Scan images; and (Below)Condition Assesment drawings of Chausath Khamba

Archival research revealed sketches dating from the early 19th century, descriptions and a continuous record of photographs from the mid 19th century.





Various stages of conservation of one dome: Numbering each stone; Dismantling the marble blocks and repairing

of cracks in the masonry; and Repair of marble blocks with indents of matching stone where these had burst by master craftsmen using tools, techniques used by the original builders and Re-installation of marble blocks in the original location.

> After removing the white cement from the broken joints, tell tails were fixed over the joints for structural monitoring for further observation by trained conservation architect and engineers. Each stone weighs from 200 to 350 kilograms and requires 4 to 5 persons to remove and stack the stone. The stones being structural stones and are interlocked with each other. Proper precision needs to follow while removing the stone without damaging the stone. Shifting of stones from the scaffolding has to be done with great care with the help of rope and requires 4-5 persons without damaging the edges of the stone. The corroded Iron dowels are then removed carefully without damaging the stone and then replaced with





The removed stones are further closely inspected before indenting repair. After examining, the stone decision on repair methodology

is taken. The process is time consuming as each stone is unique in terms of its size and curvature on both the axis.



CRAFTSMANSHIP

TERRACE

The masonry above the domes had 1 metre deep and 4" wide cracks through which the water was seeping inside the building. These cracks were required to be repaired urgently to stop further deterioration.

The 230 mm thick layer of cement concrete from the roof was removed without disturbing the underneath structure and pressure grouting was done to repair the network of cracks in the roof which were approximately 2 meters in depth. A new layer of lime concrete with additives like Jaggery and Bael fruit pulp (*Belgiri*) was laid maintaining the original slope levels. Clogged water spouts were opened to avoid rain water from stagnating.

